

## Attachment D: Examples of Erosion and Damage in the Quarry Creek Ravines



Quarry Creek nick point in Area 2 pre-disaster.

County Road 6 Bridge After the June 2014 Disaster. Note about 1 foot of the sediment had already been removed from the bridge surface.



Quarry Creek Area 3 after the June 2014 Disaster.